


GENERAL INFO:-

- 1. Lens material - Optical PC
- 2. Operating Temperature range -40° _ +110°(upper limit +130°)
- 3. Storage Temperature range -40° _ +110°(upper limit +130°)
- Average Transmittance in visible spectrum 400nm-700nm>90%
- Usage and Maintenance
- 1. If necessary, clean lenses with mild soap, water and soft cloth.
- 2. Never use any commercial cleaning solvents like Alcohol.
- 3. Handle and install lenses with wearing gloves, skin oils may Damage lenses or its optical characteristics,.

		<h1>LENS POINT (INDIA) PVT. LTD.</h1>		
Drawn By	AKASH	Title -		
Checked by	VISHAL	LP39_120X1_3030_60°_258.3268.33.7_FL10		
Approved by		Size A3	OPEN TOL.- ±0.2 MM	ALL DIMENSIONS ARE IN MM
Date	15-03-2022	Scale 1:5	MATERIAL - PC	